



NYSDEC SPILL REPORT FORM



DEC REGION:	5	SPILL NUMBER:	0485284
SPILL NAME:	GORDON FINISHING COMPANY	DEC LEAD:	MPMCLEAN
SPILL DATE:	04/02/2002	SPILL TIME:	12:00 pm
CALL RECEIVED DATE:	12/02/2004	RECEIVED TIME:	10:00 am

SPILL LOCATION

PLACE:	GORDON FINISHING COMPANY	COUNTY:	Fulton
STREET:	19 W STATE STEET	TOWN/CITY:	Johnstown (c)
		COMMUNITY:	JOHNSTOWN
CONTACT:		CONTACT PHONE:	

CONT. FACTOR:	Abandoned Drums	SPILL REPORTED BY:	DEC
FACILITY TYPE:	Commercial/Industrial	WATERBODY:	

CALLER REMARKS:

EPA performed an Emergency Removal Action at the location, removing 41 drums, 139 5g pails, and 87 <5g containers from the location. Tannery tumblers were also removed from the location. Samples outside the building was collected by EPA, no evidence of a release outside the building was identified, no response by DEC Spills occurred

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
arsenic	Hazardous Material			Ind Air,
chrome	Other			Ind Air,
formic acid	Hazardous Material			Ind Air,
sodium hydrosulfide	Hazardous Material			Ind Air,
sodium hydroxide	Hazardous Material			Ind Air,

POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
GORDON FINISHING COMPANY	NY	

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure
----------	-----------	----------	-------	--------	-------------	-----------	---------------

DEC REMARKS:

EPA perfmed ERA, Region 5 not involved directly.

RFC: NO spill outside of building identified, no DEC action necessary.

PIN

T & A

COST CENTER

CLASS:	C4	CLOSE DATE:	12/08/2004	MEETS STANDARDS:	False
--------	----	-------------	------------	------------------	-------

Created On: 12/08/2004

Date Printed: 8/8/2022

Last Updated: 12/08/2004



NYSDEC SPILL REPORT FORM



DEC REGION:	5	SPILL NUMBER:	0800997
SPILL NAME:	COMMERCIAL	DEC LEAD:	SXPASZKO
SPILL DATE:	04/24/2008	SPILL TIME:	1:39 pm
CALL RECEIVED DATE:	04/24/2008	RECEIVED TIME:	1:39 pm

SPILL LOCATION

PLACE:	COMMERCIAL	COUNTY:	Fulton
STREET:	WEST STATE STREET	TOWN/CITY:	Johnstown (c)
		COMMUNITY:	JOHNSTOWN
CONTACT:	DEPT. ENGINEER	CONTACT PHONE:	(518) 736-4014

CONT. FACTOR:	Other	SPILL REPORTED BY:	Local Agency
FACILITY TYPE:	Commercial/Industrial	WATERBODY:	

CALLER REMARKS:

TANNING MILLS ON FIRE IN TOWN AND THEY NEED DEC TO RESPOND DUE TO DYE ON STREET: BLOCKING O CATCH BASINS

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
dye	Other	0 G	0 G	Soil,

POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
COMMERCIAL	WEST STATE STREET JOHNSTOWN NY	DEPT. ENGINEER
		(518) 736-4014

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure
----------	-----------	----------	-------	--------	-------------	-----------	---------------

DEC REMARKS:

04/24/08: SP talked with secretary (Mitchell Kollar 993-5617) of Arrow at the site. Some drums of chemical but nothing hazardous. No visible dye at the time of inspection, and Kollar confirmed the dye they used in their process was non-toxic and contained no chromium or arsenic. The fire was hot and pretty much destroyed the entire building. Arrow was the only firm operating in the structure. The rest of the building was empty and being prepared for a brewery.

RFC: Based on the current information, no further action is required at this time.

PIN

T & A

COST CENTER

CLASS:	D6	CLOSE DATE:	07/02/2008	MEETS STANDARDS:	True
--------	----	-------------	------------	------------------	------

Created On: 04/24/2008

Date Printed: 8/8/2022

Last Updated: 07/02/2008